

**Double Surface Treatment:** Double Surface Treatment involves pulverization of existing distressed surface treatment followed by the placement of granular material and the application of a double surface treatment.

Road Name	From	To	Op. Area	Length	Width	Area	Total
Centreline Rd.	Pigeon Lake Rd.	Rabbit Run	CE	1900	6.50	12350	\$ 152,677
Shamrock Rd.	Centreline Rd.	Charlore Park Dr.	CC	800	6.50	5200	\$ 64,285

**Gravel Resurfacing:**The surface aggregate of an unpaved road depletes over time due to traffic. The loss of surface aggregate reduces the structural adequacy of the road base and its ability to withstand surface deformation. Gravel resurfacing offers a cost effective solution and provides stabilization to low volume unpaved roads

Road	From	To	Op. Area	Length (m)	Width	Area	Total
Vince Jones Rd.	Post Rd	Settler's Rd	CC	1400	5.20	7280	\$ 10,080

### Preparation Work for 2012 Resurfacing

Road Name	From	To	Op. Area	Length	Width	Area	Total
Cheese Factory Rd.	Post Rd.	Settlers Rd.	CE	1400	6.20	8680	\$ 21,700